

Incident: Aerotrans Cargo B744 at Frankfurt on Feb 26th 2018, engine cowl partly separated

By Simon Hradecky, created Tuesday, Feb 27th 2018 18:00Z, last updated Tuesday, Feb 27th 2018 18:00Z

An Aerotrans Cargo Boeing 747-400, registration ER-JAI performing flight ATG-4419 from Frankfurt Hahn (Germany) to Baku (Azerbaijan), was climbing out of Hahn's runway 21 when the crew stopped the climb at FL230 reporting vibrations and decided to return for a safe landing on Hahn's runway 03 about 80 minutes after departure. Part of the aft cowl of engine #1 (PW4056, outboard left hand) had separated with the access door locks appearing open.